	INFO	RMATION REPORT		This material contains in National Defense of the	
OCDABE		EMINATED BY	1 95-	meaning of the Espionac Secs. 793 and 794, the tr	
KEÇAKEL		RAL INTELLIGENCE AGENCY	1. The state of th	of which in any manner son is prohibited by law	to an unauthorized per-
UNTRY	CLITTI	TAL INTELLIGENCE AGENCY	7.0		20/(1
C	hina				
BJECT				DATE DISTRIBUTED	Sep 58
	ort Inform	nation: Dairen		NO. OF PAGES	NO OF EUCLS
¥'.				6	25X
				SUPPLEMENT TO REPORT #	
		THIS IS UNEVALUATE	ED INFORMA	ATION Y	25X1
		S OF NAVAL INTELLIGENCE FURNI SEMINATION IN ACCORDANCE WIT			
		al Designators In connection pints of interest are noted			1 3 114 1958
2. <u>A</u>	pecific po nd referre	oints of interest are noted ed to in this report by the f Anchorage	Collowing	alphabetical designree cranes	25X
	в.	Vessel's track	L. Tw	o cranes	2
	C. D.	Reduced speed Engaged tug		our or five cranes	N S
	E.		23. 51.	11 p. j 61 u	25X
	F.			oviet ship	
	G. H.	Pilot discharged Main signal station	•	oviet ship ninese ship	111.
	ī.	Secondary signal station		nk farm	/// _{25X1}
	J.	Three smokestacks		; .	Property of the
			TO N. (1) T. (2)	A.T.	
TRIBUTION	STATE	ARMY NAVY ART AIR	-B-N-T-1	A-L	× "I

NAVY review completed Approved For Release 2009/01/16 : CIA-RDP80T00246A004400120001-9

2	5	X	1	

1	C-O-N-F-I-D-E-N-T-I-A-L	
	⇒ 2 ∞	
		25X1
	the location of the main signal station at designator All berth assignments and approval of harbor movements were made there. A secondary signal station was located at designator I. This station was about 100° tall, constructed of reinforced concrete, appeared to be a dirty yellow color, and had a railed balcouncoded located to be a dirty yellow color, and had a railed balcouncoded located located to be a dirty yellow color, and had a railed balcouncoded located loc	
	d. three 50-60' smokestacks somewhere along the line designated J. These conspicuous objects were not lighted at night. they were possibly connected to canneries or used some way in the fishing industry.	25X1 25X1 25X1
5.	Pilot Data and Weather	. :
	a. 24-hour pilot service was available and compulsory. The pilot boat was a 50° diesel tug, and it had a black hull, white superstructure, and a royal blue funnel with a Red Chinese character on it. No military personnel were observed on the tug.	25X1
		25 X 1
	be frightened, unsure of their tenures as pilots, and uncertain about their place in the new Communist society. All the pilots wore heavy black coats and fuzzy fur caps with ear flaps. They wore black epaulets with gold piping and a gold star in the center.	
	b. there was considerable fog which was hazardous to navigation. Occasionally the fog would lift but visibility was always poor.	25X1
6.	Controls	
	a. At designator A a customs agent, an immigration doctor, two field securit administration police, and the agent arrived by tug. The customs agent wore a black coat, fur cap with ear flaps and a red star in the front. His epaule were black with gold piping and a red star in the center. The police wore dark khaki pants and jackets, and had red epaulets with a white band across them. They were fur caps with a red star on the front and they carried rifle	ets
		· 25 X 1

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN

NO DISSEM ABROAD

Approved For Release 2009/01/16 : CIA-RDP80T00246A004400120001-9 25X1 C-O-N-F-I-D-E-N-T-I-A-L -3b. At the first berth, three customs agents, 15 customs searchers, one health official, and three field security administration police boarded. customs searchers were blue pants, jackets, and caps with a red star on the the color of blue varied greatly from uniform to 25X1 uniform, if, indeed, they were uniforms. The senior field security administration officer spoke broken English. 25X1 all the officials were "courteous, friendly, and helpful." The officials accepted no cigarettes or liquor when it was offered, but they did accept tea. c. One soldier and one customs searcher were stationed at the foot of the gangway. The soldier wore a dark khaki uniform and a fur cap with a red star on it. He had red epaulets with a white band. Senior soldiers wore a white star instead of a white band. The soldier carried an automatic rifle. The customs searcher wore the blue uniform described above. The guard and customs searcher changed every eight hours. It was only necessary to show the pass in order to leave the ship. No surveillance boats were noted. 25X1 ₂ were approximately Harbor Craft 25X1 40-50° long and had 1500 horsepower engines, and they were painted similar no dredges, salvage equipment, ice to the pilot tug. 25X1 breakers, or lighterage in subject port or harbor. Berth Berthing area 25X1 estimated the depth of water at berth to have been 30". the pier and all its buildings had been constructed by the There were no major improvements or reconstruction on the pier. 25X1

a. is shown on diagram The two-story, dirty-yellow, reinforced concrete warehouse had wooden swinging doors. It was in good condition. The pier was illuminated at night by four lights on each side of the pier. Near vessel's berth these lights were not very 25X1 the lighting attached to the warehouse. good." 25X1 b.

The five two-ton, semi-portal, electric cranes located at These very old cranes the berth were "worthless" 25X1 were used to lift the sugar from the pier deck to the second story of the warehouse. The cranes were operated entirely by men. local cargo from the Dairen area on the pier. 25X1 berth at designator F is illustrated on diagram The pier

was illuminated by floodlights on each side of the pier at the end. The surface of the pier was cobbled and was supported by reinforced concrete pillars.

three five-ton, electric, semi-portal 9. Harbor Facilities cranes which were painted black at designator K. Two fixed, tripod, hydraulic, two-ton cranes were located at designator L, and four or five five-ton gantry cranes were at designator M.

25X

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN

8.

NO DISSEM ABROAD

25X1

C-0-N	P.T.	D B	M m	T . A . T	
Calland		2] (a) [i s	-Mo-T	∍L⇔A⇔L	í

_ 4 _

10. Clearance Facilities

the railroads and all equipment connected with them 25X1 were in "very good condition." The tracks on the pier were 3°8" gage, "just over a pace The railroad cars were about three years old and of steel construction. Each car had a small charcoal burner in it with a small smokestack protruding through the roof. The diesel engines were old but in good condition, to have been of Japanese manufacture. The car couplings were spring-operated

On Pier #2

cars were changed and switched by a diesel engine twice a day at 0500 and 2000 local time.

b. There were no trucks noted in subject port and only three 25X1 automobiles. Animal-drawn carts were used exclusively for transporting goods within the city.

c. Vessel employed workers in gangs of 30 for each hatch, each gang working in eight-hour shifts, 24 hours per day, seven days per week.

they worked hard and did a good job. A foreman was in charge of each hatch and a general foreman was overseer for the entire operation.

Neither the workers nor the foremen spoke English, and it was necessary to communicate with them through the agent. The workers were well clothed, all wearing lined pants, jackets, and fur caps. Women were employed to sweep the warehouse floors. Wages were very low the average 25X1 being 60 sens per month (slightly over US\$3). but there was an incentive bonus for efficient work and overtime.

the workers' morale was high and they seemed happy.

ll. Naval Vessels


This vessel was about 250° long and had eight decks amidships.

The hull was painted sea-green and the superstructure was cream. It had one funnel, and displayed conventional international lighting.

this "strange ship" appearing somewhat like a coastal cargo vessel, but it was a troop transport.

It was a troop transport.

is diagramed below. No naval vessels were seen in subject port, nor were any naval personnel seen ashore.



25X1

Ship Repair

had three slips which were serviced by eight 10-ton gantry cranes. No smokestacks or unusually large buildings were observed in that area, however. One
Liberty ship,

thought

be Soviet, was being repaired.

13. Merchant Vessels

C-O-N-F-I-D-E-N-T-I-A-L

25X1

NOFORN

NO DISSEM ABROAD

C-O-M-F-I-D-E-M-T-I-A-L	
- 5 -	
At	;
designator P was berthed a 1500 ton Soviet coastal freighter with two hatches, accommodations aft, and an ice breaker bow. This vessel had a "good paint job" and was "nice looking," A five thousand ton Soviet vessel was berthed at designator Q. This vessel appeared old to source but it had a good paint job and appeared to be in otherwise excellent condition. It had redar mounted above the bridge and also had an	
ice breaker bow. An old, two thousand ton Chinese Communist coastal passenger	
vessel was berthed at designator R. she could make eight knots and accommodate 150 passengers. This ship had radar and was in "perfect	
condition,"	
Petroleum and Grain At designator S a small tank farm consisting of 12 or 13 tanks approximately 30' high and 40' in diameter. They were painted silver and the paint looked reasonably fresh and neat. No grain elevator was noted in subject port.	
Shore Activities no restrictions on movements in the city. Very few military personnel were encountered on the streets. a hospital which had been	
built by the Japanese ras not crowded it was not clean	
Seamen's Club Vas a large, two-story building Large pictures of Chinese Communists hung on the walls. Propaganda was available but was not forced on anyone. Liquor was served at a small bar, a dining room served meals at a reasonable	. 25
Miscellaneous a. all guards, military personnel, civil officials, and port administrators whom he encountered were Chinese. No	
Soviet flags were seen in the port and Dairen was by all indications under the administration and control of Red China.	
b. low level of industrialization in Dairen.	
no evidence of the manufacture or stockpiling of naval weapons in or near Dairen.	
c. there was an adequate supply of electricity in subject port but the power was low. he lights cast	
a "wellow glow." Everything was lighted at night, including the piers and	
all streets. However, the lights were too sparsely located and too dim to provide illumination of the quality and quantity found in US cities, and left enough dark and shadowy areas to provide cover for cutthroats and pilferers.	,
d. the main objective of the Communist government	
was to feed and clothe her citizens. This objective takes precedence over construction and expansion of industry, and although every-	
one is very poor, the people appeared to be reasonably well fed and clothed. The Chinese people "became so disgusted with every form of government that	
one is very poor, the people appeared to be reasonably well fed and clothed.	
one is very poor, the people appeared to be reasonably well fed and clothed. The Chinese people "became so disgusted with every form of government that they were willing to give Communism a try as a sort of desperate hope." Communism as practiced in China is different from the Soviet brand of Communism to which Western minds are accustomed, and	

NOFORN

25X1

C-O-N-F-I-D-E-N-T-I-A-L


-6-


	although the Chinese do not love the Soviets, they do There is a strong anti-US feeling in China, mese being insulted and angered because the US government	05)
refuses to recognize t	the Communist government. The people	25X
f. children were observed	few people in Dairen speak English. Groups of a patrolling the streets with long sticks to kill birds	25>
which were labeled "pe the anti-bird campaign	eople's enemies" because they ate grain.	25X
All imp	portant buildings in Dairen date from the Japanese occu- nstruction has been undertaken.	25)
		25)

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN

NO DISSEM ABROAD





25X1



